

| | Type | Hits | Search Text | DBs |
|---|------|--------|--|-------|
| 1 | IS&R | 251 | ("438/612").CCLS. | USPAT |
| 2 | BRS | 4179 | "bonding pad" | USPAT |
| 3 | BRS | 950134 | (PILLAR OR REINFORCEMENT OR STUD OR SUPPORT) | USPAT |
| 4 | BRS | 140 | ((("BONDING PAD") WITH ((PILLAR OR REINFORCEMENT OR STUD OR SUPPORT))) | USPAT |
| 5 | BRS | 4 | ((438/612.CCLS.) AND (((("BONDING PAD") WITH ((PILLAR OR REINFORCEMENT OR STUD OR SUPPORT)))))) | USPAT |

| | Time Stamp | Comments | Error Definition | Errors |
|---|---------------------|----------|---------------------|--------|
| 1 | 2000/07/19 14:55 | | | 0 |
| 2 | 2000/07/19 15:18 | | | 0 |
| 3 | 2000/07/19 14:33 | | | 0 |
| 4 | 2000/07/19 14:34 | | | 0 |
| 5 | 2000/07/19 14:34 | | | 0 |

| | Type | L # | Hits | Search Text | DBs |
|---|------|-----|------|--|-------|
| 1 | IS&R | L1 | 1 | ("5149674").PN. | USPAT |
| 2 | BRS | L4 | 68 | "bonding pad" with (nickel or palladium) | USPAT |
| 3 | BRS | L5 | 53 | "bond pad" same "barrier layer" | USPAT |
| 4 | BRS | L6 | 16 | 5 same (tantalum titanium tungsten chromium) | USPAT |
| 5 | IS&R | L7 | 1 | ("5942448").PN. | USPAT |
| 6 | IS&R | L9 | 1 | ("5290588").PN. | USPAT |
| 7 | IS&R | L8 | 1 | ("5834365").PN. | USPAT |

| | Time Stamp | Comments | Error Definition | Errors |
|---|---------------------|----------|---------------------|--------|
| 1 | 2000/07/19 15:18 | | | 0 |
| 2 | 2000/07/19 15:21 | | | 0 |
| 3 | 2000/07/19 15:22 | | | 0 |
| 4 | 2000/07/19 15:27 | | | 0 |
| 5 | 2000/07/19 15:29 | | | 0 |
| 6 | 2000/07/19 15:30 | | | 0 |
| 7 | 2000/07/19 15:31 | | | 0 |